


## Crimping pliers for industrial use PV-CZ...

These tools are to be used for the assembly of UL and TÜV-approved products. These are suited for the processing of high numbers of pieces and can be adjusted to the product to be processed with the help of changeable locators and crimp inserts.

### PV-CZM...



Order No.	Type	Designation	Pliers cross sections		Connector system	Crimping pliers type	 Assembly instruction
			mm <sup>2</sup>	AWG			
<b>32.6020-16100A</b>	PV-CZM-16100A	Crimping pliers incl. Locator and crimping die	2.5; 4; 6	14; 12; 10	MC4 AU	For closed crimp contacts (O-Crimp)	MA260
<b>32.6020-18100</b>	PV-CZM-18100		2.5; 4	14; 12	MC4	For open crimp contacts (B-Crimp)	MA251
<b>32.6020-19100</b>	PV-CZM-19100		2.5; 4; 6	14; 12; 10	MC4	For open crimp contacts (B-Crimp)	MA251
<b>32.6020-20100</b>	PV-CZM-20100		4; 10		MC4	For open crimp contacts (B-Crimp)	MA251
<b>32.6020-21100</b>	PV-CZM-21100		6; 10		MC4	For open crimp contacts (B-Crimp)	MA251
<b>32.6020-22100</b>	PV-CZM-22100			12; 10; 8	MC4	mixed	MA251
<b>32.6020-23100</b>	PV-CZM-23100			14; 12; 10; 8	MC4	For closed crimp contacts (O-Crimp)	MA251
<b>32.6020-40100</b>	PV-CZM-40100		2.5; 4	14; 12	MC4-Evo 2	For open crimp contacts (B-Crimp)	MA251
<b>32.6020-41100</b>	PV-CZM-41100		2.5; 4; 6	14; 12; 10	MC4-Evo 2	For open crimp contacts (B-Crimp)	MA251
<b>32.6020-42100</b>	PV-CZM-42100		4; 10	12; 8	MC4-Evo 2	For open crimp contacts (B-Crimp)	MA251
<b>32.6021-16100</b>	PV-ES-CZM-16100	Crimping die	2.5; 4; 6	14; 12; 10	MC4	For open crimp contacts (B-Crimp)	MA260
<b>32.6021-18100</b>	PV-ES-CZM-18100		2.5; 4	14; 12	MC4	For closed crimp contacts (O-Crimp)	MA251
<b>32.6021-19100</b>	PV-ES-CZM-19100		2.5; 4; 6	14; 12; 10	MC4	For open crimp contacts (B-Crimp)	MA251
<b>32.6021-20100</b>	PV-ES-CZM-20100		4; 10		MC4	For open crimp contacts (B-Crimp)	MA251
<b>32.6021-21100</b>	PV-ES-CZM-21100		6; 10		MC4	For open crimp contacts (B-Crimp)	MA251
<b>32.6021-22100</b>	PV-ES-CZM-22100			12; 10; 8	MC4	mixed	MA251
<b>32.6021-23100</b>	PV-ES-CZM-23100			14; 12; 10; 8	MC4	For closed crimp contacts (O-Crimp)	MA251
<b>32.6021-40100</b>	PV-ES-CZM 40100		2.5; 4	14; 12	MC4-Evo 2	mixed	MA251
<b>32.6021-41100</b>	PV-ES-CZM 41100		2.5; 4; 6	14; 12; 10	MC4-Evo 2	For open crimp contacts (B-Crimp)	MA251
<b>32.6021-42100</b>	PV-ES-CZM 42100		4; 10	12; 8	MC4-Evo 2	For open crimp contacts (B-Crimp)	MA251
<b>32.6040</b>	PV-LOC	Locator	2.5; 4; 6; 10	14; 12; 10	MC4	For open crimp contacts (B-Crimp)	MA251
<b>32.6055</b>	PV-LOC-B			12; 10; 8	MC4	mixed	MA251
<b>32.6056</b>	PV-LOC-C		2.5; 4; 6; 10	14; 12; 10	MC4-Evo 2	For open crimp contacts (B-Crimp)	MA251
<b>32.6074</b>	PV-LOC-D			14; 12; 10; 8	MC4	For closed crimp contacts (O-Crimp)	MA251